

SERVICE LETTER

SL-SI610-200**TITLE**

AVAILABILITY OF IMPROVED DESIGN SKYSTEP SUPPORT CABLE ASSEMBLIES

EFFECTIVITY**MODEL**

500 Series - STC ST04016NY
501, 551 – STC SA04176NY
525 Series – STC SA04015NY
Skystep Serial Numbers 19-001 thru 25-181

SERIAL NUMBERS

ALL
ALL
ALL

REVISION AND ISSUE DATE

REV #	DATE	DESCRIPTION	APPROVED BY
IR	01/13/2026	Initial Revision	E.W. King III

1. SUBJECT

1.1 Availability of New and Improved Skystep Support Cable Assemblies.

2. COMPLIANCE

2.1 Recommended- This service document can be accomplished at the discretion of the owner.

3. COST

3.1 The cost for a set of the improved design support cable assemblies is \$1,150.00.

4. LOCATION

4.1 These new support cable assemblies can be installed by any appropriately certificated agency, technician or repairman.

5. CONTACT

5.1 For additional information regarding purchasing this new product:

Skyway Group, Inc.
122 Howard Langford Drive
Uvalde, TX 78801
Phone: (830) 900-7032, Ext. 303
E-mail: ino@skyway-mro.com

SERVICE LETTER




Figure 1
Support Cable Assemblies

6. SERVICE / ACTION

6.1 All customer owned Skystep Assemblies meeting the Effectivity shown on sheet 1 and installed prior to DEC/2025 are eligible for to install the improved design replacement forward and aft Support Cable Assemblies.

6.2

MATERIAL - Cost and Availability *

PART NUMBER

COST

500 Series and 501, 551

SL-SI610-200-1, Support Cable Assy. - Kit	\$1,150.00
---	------------

525 Series

SL-SI610-200-2, Support Cable Assy. - Kit	\$1,150.00
---	------------

* Please contact Skyway Parts for current cost and availability of kits listed in this service letter. Phone 1-830-900-7032, Ext. 303 or send an Email to: info@skyway-mro.com.

Based on availability and lead times, parts may require advanced scheduling.

--- END ---